



Mercedes-Benz

Mercedes-Benz Wollongong

Authorised Mercedes-Benz  
Sales, Service & Parts

SERVICE TAX INVOICE

258807

C1 Customer (Cash)		REPAIR ORDER No: JC13307995			PAGE: 1	
CUSTOMER: MR GARY NELSON 18 Wollongong Street Shellharbour NSW 2529		DATE: 22/04/2015	TIME IN: 8:00 AM	TIME OUT: 5:00 PM	KILOMETERS: 237737	ADVISER: RC
		VEHICLE: 313 SWB VAN FL			MONTH/YEAR	AIR:
		REG. No: BY07FB	STOCK No:	SELLING DEALER:		
CUSTOMER No: 58658	VIN: WDB9036622R772318			ENGINE No: 61298151021420		
CONTACT NAME: Mr Gary Nelson		COLOUR/TRIM /			ORDER No:	
CONTACT No 1:	CONTACT No 2: 0414295500	WARR. EXP. DATE:	WARR. EXP. KM:	EXT. WARR. EXP. DAT	EXT. WARR. EXP. KM	FIRST REG. DATE: 12/12/2005
<input type="checkbox"/> CASH	<input type="checkbox"/> FLEET CARD	<input type="checkbox"/> CREDIT CARD	<input type="checkbox"/> ACCOUNT	REF. NO#		

PRICE QTY/HRS AMOUNT

JOB DETAILS

JOB 1 CHECK COMPUTER EDU REPORT CAMSHAFT NOT REGISTERIN 272.72

Ran a short test. Found numerous fault codes relating to the cam/crank shaft sensor plausibility faults. Tested wiring, OK. Connected ossiliscopes and checked pattern. Also could not fault. Recommend as a first step to replace the ~~camshaft~~ sensor as it may be intermittantly dropping out.  
*crankshaft.*

Also found a fault code relating to the boost pressure control. Vehicle requires replacement of the boost pressure controller.

JOB 1 SUBTOTAL 272.72

JOB DETAILS

JOB 2 CHECK OVER VEHICLE TO MAKE SURE ALL OK 136.37

Gave vehicle a minor check over:  
 \*\*Leaking front shock  
 \*\*Broken CV boots  
 \*\*Excessive play in front ball joints URGENT!!!  
 \*\*Rear shock bushings are worn

Find attached schedule for services to consider.

JOB 2 SUBTOTAL 136.37

LABOUR \$409.09  
 SUBTOTAL \$409.09  
 GST \$40.91  
 TOTAL INCLUDES GST \$450.00

\*\*\*\*\* CONTINUED \*\*\*\*\*

Cnr Bourke & Flinders Street  
 Wollongong NSW 2500  
 Tel + 61 2 4228 8933  
 Fax + 61 2 4228 8944  
 www.mbwollongong.com.au  
 ABN 22 002 019 598 / ACN 002 019 598  
 LMCT/Dealer Licence Number MD8686

WDB9036622R772318	Model series/model designation	Sprinter
Order number	License plate	

Filter status: All control units

CR common rail				- f -
MB number	HW version	SW version	Diagnosis version	Pin
6121537279	14.2000	38.2003	0/131	14
Code	Text			Status
P1354-002	Synchronization between crankshaft and camshaft - Frequency of camshaft signal is too high.			STORED
P1354-016	Synchronization between crankshaft and camshaft - No crankshaft signal.			STORED
P1354-064	Synchronization between crankshaft and camshaft - No camshaft signal.			STORED
P1470-004	Charge pressure control valve - Cable has $\Gamma$ $\Gamma$ +.			STORED

KI instrument cluster				- ✓ -
MB number	HW version	SW version	Diagnosis version	Pin
0014468521	00.2012	00.2007	7/07	12

WSP immobilizer				- ✓ -
MB number	HW version	SW version	Diagnosis version	Pin
0335456032	26.2002	24.2002	0/03	4

ABS anti-lock braking system				- ✓ -
MB number	HW version	SW version	Diagnosis version	Pin
0004465689	42.2001	40.2001	0/08	13

ABW airbag with window airbag				- ✓ -
MB number	HW version	SW version	Diagnosis version	Pin
0028203826	11.2000	29.2000	2/02	8

ARS All-wheel system				- ✓ -
MB number	HW version	SW version	Diagnosis version	Pin
9014460152	49.1999	10.2001	0/03	13

ZV central locking system				- ✓ -
MB number	HW version	SW version	Diagnosis version	Pin
0004461019	25.2003	16.2002	0/0	6

CAN bus				- ✓ -
MB number	HW version	SW version	Diagnosis version	Pin
				0

Tuesday, April 21, 2015 11:40:52

Page 1/2

03/2015 (2015-01-15)\AddOns: (3626) (3627) (4265) (4266) (4269) (4271) (4273) (4274) (4289) (4293) (4295) (4298) (4302) (4304) (4305) (4312) (4314) (4316) (4317) (4325) (4328) (4334) (4336) (4342) (4344) (4345) (4349) (4352) (4353) (4354) (4355) (4357) (4359) (4362) (4364) (4365) (4367) (4373) (4374) (4376) (4377) (4383) (4385) (4387) (4389) (4390) (4391) (4392) (4393) (4394) (4396) (4397) (4399) (4403) (4404) (4405) (4409) (4410) (4411) (4414) (4415) (4419) (4421) (4422) (4424) (4425) (4428) (4429) (4431) (4437) (4446) (4447) (4449) (4452) (4455) (4457) (4460)